

PUBLIC WORKS DEPARTMENT  
DIRECTORATE OF BOILERS

FROM

TO

THIRU.R.SUNDAR, M.Tech.,  
DIRECTOR OF BOILERS,  
First Floor (North Wing),  
P.W.D. Office Compound,  
Chepauk, CHENNAI - 600 005.

M/s. Hofincons Infotech and  
Industrial Services,  
140/98, Sidco Industrial Estate,  
Ambattur,  
Chennai-600 098.

Letter No. BL1 / 3355-M / 2015, Dated 17 .08.2015.

Dear Sirs,

Sub: Firm Registration - as Class-1 Boiler Repairer under  
Indian Boiler Regulations, 1950 - Firm Approval - Orders  
issued - Regarding.

Ref: 1. Your Letter No. NIL/Dt.25.07.2015.  
2. Inspection of the firm by Director of Boilers, Tamil  
Nadu, Chennai - 5 on 12.08.2015.

-----

With reference to your letter cited and based on the brief history of the firm furnished by you and further to the inspection of your firm by the Director of Boilers, Tamil Nadu, Chennai-5 on 12.08.2015, your firm is hereby approved as Class-I Boiler Repairer (Boiler Pressure  $>40$  Kgs/Cm<sup>2</sup> and  $<125$  Kgs/Cm<sup>2</sup>) as per the regulation 392 (3)(i) and Serial Number 3 (b) of form XVIII of Indian Boiler Regulations, 1950.

The Welding work involved in the Boiler Repairs/Steam Pipeline Erection works should be carried out only by welders qualified under Indian Boiler Regulations, 1950. Hence, you may please qualify some of your welders under Indian Boiler Regulations, 1950 in this state, for plate, pipe and tube welding.

Any boiler repair works should be carried out only after the approval given by the Director of Boilers, to the Boiler Owners. The pipeline erection work should also be carried out only after the approval of steam pipeline layout drawings by the Director of Boilers, Tamil Nadu for the Boiler Owners.

You are requested to maintain the quality and standard of work to the utmost satisfaction of the Boiler Owners and as well as to this Directorate. If any adverse report is received either from the owner or from the inspection officer, this order is likely to be withdrawn.

A model form of commencement and completion report on repairs is enclosed herewith. Commencement and completion report on repairs should be submitted to this office, as well as to the Deputy Director of Boilers / Senior Assistant Director of Boilers concerned as and when you undertake repairs to Boiler. Fortnightly report on repairs should also be submitted to this office regularly. This may be followed strictly.

..2..

/2/

You are informed that as Class-I Boiler Repairer you should always have sufficient number of welders qualified under Indian Boiler Regulations, 1950 for Carbon Steel Plate and Alloy Steel Pipe and Tube in TIG Welding in this state.

The firm registration order now issued is valid for the period from 12.08.2015 to 30.06.2016.

You are requested to remit a sum of Rs.2000/- (Rupees Two Thousand Only) towards the firm registration fees and send the Original Treasury Chalan to this office, immediately.

You are informed that you should apply for the firm registration renewal every year, promptly before the expiry date, duly remitting Rs.1000/- (Rupees one thousand only) towards the firm renewal fees and send the Original Treasury Chalan to this office.

You are also informed that you should always have two welders qualified under Indian Boiler Regulations, 1950 for Carbon Steel Plate and Alloy Steel Pipe and Tube in TIG Welding, with valid certificates, for considering firm registration renewal.

The receipt of this order please be acknowledged.

Yours faithfully,



DIRECTOR OF BOILERS,  
TAMILNADU, CHENNAI-5.

Encl: 1. Commencement report. (model)  
2. Completion report. (model)  
3. Blank Chalan.

Copy to: The Deputy Director of Boilers, Chennai Circle, Chennai-05.